


battery-check button

power switch

bias-monitor port
(output = 1 mV/mA)

RF output
(Wiltron® K Connector)



fiber-optic input
connector (FC)

