


battery-check button

power switch

bias-monitor port  
(output = 1 mV/mA)

RF output  
(Wiltron® K Connector)



fiber-optic input  
connector (FC)

2.25"  
(57.1)

3.27" (82.9)

2.00"  
(50.8)

2.00"  
(50.8)

remove two screws  
to replace 9-V battery

 New Focus™